



Product Alert 52

Product	6G and 12G QXS-312, QXS-412, QXS-456, QXS-656 and QXS-484 Arrays
Summary	The Disk Scrub Interval setting might cause undue wear on drives and impact performance.
Date	July 2020

Contents

Overview	2
Symptoms	2
Solution	2
Workaround	2
Contacting Quantum	3

© 2020 Quantum Corporation. All rights reserved. Your right to copy this manual is limited by copyright law. Making copies or adaptations without prior written authorization of Quantum Corporation is prohibited by law and constitutes a punishable violation of the law. Artico, Be Certain (and the Q brackets design), DLT, DXi, DXi Accent, DXi V1000, DXi V2000, DXi V4000, DXiV-Series, FlexSync, FlexTier, Lattus, the Q logo, the Q Quantum logo, Q-Cloud, Quantum (and the Q brackets design), the Quantum logo, Quantum Be Certain (and the Q brackets design), Quantum Vision, Scalar, StorageCare, StorNext, SuperLoader, Symform, the Symform logo (and design), vmPRO, and Xcellis are either registered trademarks or trademarks of Quantum Corporation and its affiliates in the United States and/or other countries. All other trademarks are the property of their respective owners. Products mentioned herein are for identification purposes only and may be registered trademarks or trademarks of their respective companies. All other brand names or trademarks are the property of their respective owners. Quantum specifications are subject to change.

Overview

Affected Systems

- 6G and 12G QXS-312, QXS-412, QXS-456, QXS-656 and QXS-484 arrays.

Problem Description

The disk scrub background process that cleans up media errors can run more often than necessary when using 3.5" 7200 RPM NL-SAS disks, which can potentially cause undue wear on the drives and have a negative impact on performance.

-
- i Note:** If you are impacted by this issue, please call Quantum Support and reference Product Alert52. See [Contacting Quantum on the next page](#).

Symptoms

The following symptoms might be present if the system enters this state:

1. Higher than expected drive failures.
2. Degraded IO performance.

Solution

Quantum recommends you change the background scrub process frequency from the current default value of 24 hours to 360 hours.

Workaround

To change the background scrub process frequency to 360 hours, run the following CLI command on either of the QXS controllers:

```
# set advanced-settings background-scrub-interval 360
```

Contacting Quantum

Contacts

For information about contacting Quantum, including Quantum office locations, go to:

<https://www.quantum.com/aboutus/contactus/index.aspx>

For further assistance, or for training opportunities, contact the Quantum Customer Support Center:

Region	Support Contact
North America	1-800-284-5101 (toll free) +1-720-249-5700
EMEA	+800-7826-8888 (toll free) +49 6131 324 185
Asia Pacific	+800-7826-8887 (toll free) +603-7953-3010

For worldwide support:

<https://www.quantum.com/serviceandsupport/get-help/index.aspx#contact-support>

Comments

To provide comments or feedback about this document, or about other Quantum technical publications, send e-mail to:

doc-comments@quantum.com